

Are You Properly Suited For Welding?



Always wear the following:

- **Impact and heat resistant eye protection and nonflammable helmet for gas welding.**
- **Eye protection and helmets which are resistant to impact, heat, electricity and fire.**
- **Long Sleeve shirts which fit close to the wrists and neck.**
- **Work boots or high shoes which can be partially covered with pant legs.**
- **Leather sleeves, leggings and aprons for extra hot jobs.**
- **Dry welders gloves.**